




HDS TRADING CORP.

New Jersey Office
1305 Jersey Avenue
North Brunswick, NJ 08902
tel 732.418.0418 | fax 732.418.0414


Assembly Instruction

4-TIER WIRE SHELVING

1. Please read the assembly instructions carefully before assembling and check all the parts.
2. Please check the parts quantity
3. Do not touch the cut surface of tube




Parts Identification




A

4PCS



B

4PCS



C

4PCS



D


4PCS



E


32PCS

Step 1




Put part (E) into the hole of part (A), please noted the gap of part (E) must be up.

Step 2




Put metal net (D) into tube (A), and arrive to the position of part (E), and note the diameter size of metal net (D).

Step 3




Insert tube (B) into tube (A), aim at the hole.

Step 4




Fasten part (E) into the hole of part (B), then put the metal net (D) into tube (B).

Step 5



Insert tube (C) into tube (B), fasten the hole of part (B&C) with part (E), then put metal net (D) into tube (C).

Step 6



Fasten part (E) into the top hole of tube (C), then put metal net (D) into tube (C).

Step 7

